

MASSACHUSETTS INSTITUTE OF TECHNOLOGY
A. I. LABORATORY

Artificial Intelligence
Memo No. 273

January 1973

THE LITTLE ROBOT SYSTEM

David Silver

Work reported herein was conducted at the Artificial Intelligence Laboratory, a Massachusetts Institute of Technology research program supported in part by the Advanced Research Projects Agency of the Department of Defense and monitored by the Office of Naval Research under Contract Number N00014-70-A-0362-0003.

Reproduction of this document, in whole or in part, is permitted for any purpose of the United States Government.

Table of Contents

General description	Page - 1
Using the Little Robot in LISP	Page - 4
LISP Functions	Page - 6
The I/O Variables	Page - 8
Examples	Page - 12

General description of the Little Robot System

The Little Robot System provides for the I.T.S. user a medium size four degree of freedom six axis robot which is controlled by the PDP-6 computer through the programming language Lisp. The robot includes eight force feedback channels which when interpreted by the PDP-6 are read by Lisp as the signed forces applied to the end of the fingers. The first six forces are the X, Y and Z forces and the torques around X, Y and Z. The other two forces are the grippers and the vice grippers. The three X, Y and Z forces and three torques are computed from six sensors read in from six L.V.D.T.s (Linear Variable Differential Transformers) arranged three in the vertical and three in the horizontal plane within a stress strain spring loaded wrist. The grip is read in from a strain gauge mounted on the stationary reference finger. The relative position between the motor shaft and the vice shaft is determined through means of two potentiometers to measure the vice force. The two shafts are coupled by a spring.

The force feedback wrist has a dynamic range of about one pound and a resolution of about 0.25 ounces with not more than one ounce of hysteresis. The grip can measure one pound of gripping force and the vice can measure about three pounds of gripping force.

The robot has its six axes split up into two parts. The first half consists of a nine square inch plate which moves in two perpendicular directions for X and Y. The computer controlled vice is mounted on the plate in one corner. The other half consists of the Z axis which is mounted over the plate. The Z axis hangs down over the plate and has a vertical travel of five inches. On the end of the Z axis is mounted the stress strain wrist and on the end of the wrist is mounted the hand which can rotate and grip. Until a hardware modification is made only the center six of the nine square inch work-space can be used.

The three main axes (X,Y and Z) have a resolution of 0.001 inches and a positioning repeatability of plus or minus 0.003 inches. The X,Y plate is flat and level with respect to the end of the fingers to less than 0.010 inches. The robot can be positioned anywhere within the six by six inch work space in less than twenty seconds.

The Little Robot Controller is mounted on the right hand side of the table where the robot lives. The plexiglass panel on the front of the controller has some light's, switches, and a whistle which goes "feed" when the robot feels pain. The controller contains six power amplifiers so the computer can control the speed of each motor associated with each of the six axes. It also contains appropriate interfacing of six high resolution potentiometers to measure the position of the six axes, making it possible for the computer to servo to the desired positions of all six axes.

Six L.V.D.T. amplifiers, a strain gauge amplifier and a differential amplifier are contained within the controller to interface the wrist, reference finger, and the vice force input. Also contained in the controller are some electronics which monitor all eight forces felt by the robot. If any of the forces exceeds the threshold of pain, the controller is told to shut off all six motors and to start feeding the whistle. Because of the simple minded nature of this safety feature, the robot cannot hack away from pain and will get itself latched no merely by squeezing too hard with the grip or vice, or by moving the arm down into the table, etc. This latching up problem is something that the user shouldn't have to encounter because the program running in the NDP-6 contains a model of pain which is both aware of the latch up problem and allows the robot to move away from pain. If the robot does get into this latched up state it should be regarded as a hug in the Little Robot System and you should turn off the controller. By the way, the whistle will still continue to feed so you might also flip off the switch labeled "ALARM" before it drives you nuts.

Using The Little Robot in Lisp

Start the PDP-6 running, then type:

```
LISP
```

```
(FASLOAD NINOPR FASL COM)
```

```
(OPENMINI)
```

```
(SETB CALB -1)
```

Sometimes LISP and the Compiler are incompatible, in which case when you do the FASLOAD, LISP will type out a warning message. Try DLISP, and if that fails then try (UREAD NINOPR >).

OPENMINI will return NIL after the PDP-6 is loaded and running.

"CALB" will become zero when the calibration is done.

Do not type on the teletype or lean on or bump the table while the robot is calibrating itself! If you should disturb the robot while it is calibrating itself, then recalibrate. Part of the calibrating sequence consists of mapping the null force for all orientations of the hand. Therefore, bumping the arm while calibrating will cause the robot to feel a ghost force whenever it passes through that same orientation. The robot can feel building tremors.

Before you flip the motor switch to on always check the following:

- 1) Check the five red power supply indicator bulbs labeled +15 -15 +10 +25 -25 . If any of these indicators are out, turning the motor switch on can cause damage to the hardware.
 - 2) Check the switch behind "ALARM" and make sure it is on. If when you flip it on the alarm starts to beep, or any other time the alarm starts beeping give up, and let me know. Make sure to flip off the alarm switch and the motor switch before you leave.
 - 3) Check and make sure that LISP has returned NIL after you have typed (OPENMINI) or (REOPENMINI).
- Flip the motor switch on. The initial state of the Little Robot variables are such that the arm will assume a position which is centered over the table as soon as the motor switch is turned on.

Theoretically, the Little Robot can not be damaged under program control. But please note the following: try not to apply more than one or two pounds of force to either the X,Y head or the hand and wrist. When setting up the scene, for example, if your shirt sleeve were to get caught on part of the hand as you pulled your hand away, you might sprain the robot's wrist. Remember that the wrist is only supporting the hand with four pieces of 0.04 inch piano wire.

LISP Functions

SETM - The LISP function SETM (SET Mini) of two arguments is used to set variables. For example, (SETM XPOS 3.0) will move the arm to a position three inches on the X axis.

GETMF - The function GETMF (GET Mini Floating point) of one argument is used to read variables. For example, if XPOS is 3.0, (GETMF XPOS) might return the value 2.999 meaning that the potentiometer is measuring the X axis to be 0.001 inches from its destination.

GETM - (GET Mini fixed point). Care should be taken to read fixed point variables with GETM and floating point variables with GETMF.

WAIT - The function WAIT of one argument first waits for the variables in the PDP-6 to become consistent and then evaluates its argument every thirtieth of a second and will sleep until evaluating the argument returns T.

SEQ - The function SEQ (Sort of Equal) of three arguments returns the value T when the first two arguments are equal to within the tolerance of the third argument, otherwise NIL. The following example will first set the arm's destination to 1.5 inches above the table and will then sleep until the arm actually gets to within three mils of 1.5 inches above the table.

```
(SETN ZDFS 1.5)
(WAIT '(SEQ (GETMF ZDFS) (GETMF ZPOS) 0.003))
```

OFFNMINI - Type (OPENINI) to load and start the PDP-6 robot program.

REOFFNMINI - Type (REOPENINI) to reload and start the PDP_6 program.

CLOSEINI - Type (CLOSEINI) to close the PDP-6.

The I/O Variables

You may find the list of variables to be somewhat random because of the flags and the apparent redundancy of some of the variables. The following list is the subset of all the variables which should most commonly be used. You may need to use some of the other variables if you require tolerances which are close to or are limited by the specifications listed in the beginning.

Output variables (Abbreviated description)

CALB - When set to -1 runs Calibration program.
 RESET - When set to -1 Resets the variables.
 XDES-VDES - Floating point Destination.
 XFDS-VFDS - Fixed point Force Destination.
 XFRE-VFRE - When set to 0 serves to FDS.
 When set to -1 serves to FDS.

Input variables (Abbreviated description)

XPOS-VPOS - Floating point Positions.
 XFRS-VFRS - Fixed point Forces.
 XTRC-VTRC - Fixed point Torques.
 XDLT-VDLT - Fixed point Deltas.

Input variables

TIC Is incremented every 1/60 sec in the variables update loop.

Done -

XDLT The Deltas are fixed point numbers which are the differences between the destinations and the current positions in pot units. (Pot units being the numbers sent out and read in from the A/D and D/A multiplexor.)

YDLT

ZDLT

RDLT

ODLT

VDLT

XPOS The Positions are floating point numbers which
 YPOS are the current positions of the axes as seen by the
 ZPOS potentiometers in units of inches for the linear
 RPOS axes and radians for the rotate axis.
 GPOS
 VPOS

XFORS The Forces are fixed point numbers which are the
 YFORS signed forces being applied to the hand.
 ZFORS These numbers are corrected to read closer to zero
 RFORS for all orientations of the hand.
 GFORS
 VFORS

XTORC The Torques are fixed point numbers which are the
 YTORC magnitude and sign of the torques around the three
 ZTORC force axes. For example if the hand was rotating
 RTORC a nut for the purpose of screwing it on to a bolt,
 GTORC you could get the torque being applied to the bolt
 VTORC from ZTORC.

XVLS The Velocities are fixed point numbers which are
 YVLS the velocities of the axes.
 ZVLS
 RVLS
 GVLS
 VVLS

IRFORS The Raw Forces are fixed point numbers read in
 ZRFORS by the A/D. They are the forces measured by the
 3RFORS six L,V,D,T's, in the wrist.
 4RFORS
 5RFORS
 6RFORS
 7RFORS A/D input from strain gauge.
 8RFORS A/D input from pot assembly.
 VRFORS

1ZFORS The Zeroed forces are fixed point numbers which are
 2ZFORS the forces measured by the L,V,D,T's strain gauge and
 3ZFORS note which are corrected to read closer to
 4ZFORS zero for all orientations of the hand.
 5ZFORS
 6ZFORS
 7ZFORS
 8ZFORS
 9ZFORS
 VZFORS

XPPDS The Pot Positions are fixed point numbers read in
 YPPDS from the pots by the A/D,
 ZPPDS
 RPPDS
 OPPDS
 VPPDS

Output Variables

GAIN Calb should be set to -1 first thing after
 ineding and opening the Little Robot for
 the purpose of calibrating and zero centering
 the force inputs. Calb will become zero again
 when the calibration is completed.

XPDSS The Pot unit Destination specified in fixed point
 YPDSS will have effect only if FRE (Limp mode flag)
 ZPDSS is zero and CLMD (Calibrate mode flag) is zero.
 RPDSS
 OPDSS
 VPDSS

XGAN The gains are fixed point numbers which determine
 YGAN the position servo gain only when FRE (Limp mode flag),
 ZGAN is zero.
 RGAN
 OGAN
 VGAN

XFGN The Force Gains are fixed point numbers which
 YFGN determine the gain in limp mode and are
 ZFGN only effective when FRE (Limp mode flag) is -1.
 RFGN
 OFGN
 VFGN

XFRE When FRE (Free) is set to -1 the axis
 YFRE is in limp mode and the axis will servo to
 ZFRE a desired force FDS (Force destination).
 RFRF
 OFRE
 VFRE

XDES The Destination is specified in floating
 YDES point in units of inches for the linear axes
 ZDES and radians for the rotate axis. DES is effective
 RDES only when FRE (Limp mode flag) is zero
 ODES and CLMD (Calibrate mode flag) is -1.
 VDES

XCMD CLMD is the suffix for six flags
 YCMD which when set to zero cause the arm to
 ZCMD servo to the PDPS (Pot unit Destination)
 RCMD and when CLMD is set to -1 causes the arm
 GCMD to servo to DES (Floating point Destination),
 VCMD

XFDS The FDS (Force Destination) is effective
 YFDS when FRE (Limn mode flag) is -1. FDS is set
 ZFDS to a fixed point number causing the axis to
 RFDS move in such a way so as to servo the force
 GFDS to the FDS.
 VFDS

ARMON is a flag which when set to -1 softwarely
 turns the arm on and when set to zero
 turns the arm off.

RESET is a flag which when set to -1 restores
 all the robot variables to their
 initial state. Reset will return to zero
 when the reset is done.

EXAMPLES

```

(SETQ UP 4.0)
(SETQ OPN 1.5)
(SETQ SQZ 2000)
(SETM RFSFT -1)
(WAIT '(ZFRDP (GETM RFSFT)))
(SETM XDES 0)
(WAIT '(SEQ (GETM RPOS) 00,005))

(DEFUN MOVETO (X Y Z)
  (SETM ZDES UP)
  (WAIT '(SEQ (GETM ZPOS) UP 0.005))
  (SETM XDES X)
  (SETM YDES Y)
  (WAIT '(AND (SEQ (GETM XPOS) X 0.005) (SEQ (GETM YPOS) Y 0.005)))
  (SETM ZDES Z)
  (WAIT '(SEQ (GETM ZPOS) Z 0.005))
  NIL)

```

```
(DEFUN GRIP ()  
  (SETF GFDS SIZE)  
  (SETF GFRE -1)  
  (WAIT '(SEQ (GETH GDLT) 0 20)  
  NIL)
```

```
(DEFUN UNGRIP ()  
  (SETF GRES OPEN)  
  (SETF GFRE 0)  
  (WAIT '(SEQ (GETH GDLT) 0 20 )  
  NIL)
```